


WFO-3169-59

12 May 1959

MEMORANDUM FOR THE RECORD

SUBJECT: P2V7 ^{or derivative} Cooperation Meeting

1. P2V7 ^{or derivative} Cooperation Meeting was held 0930, 7 May 1959. The following were in attendance:



25X1

2. There were no errors or omissions in the minutes of the meeting held 30 April 1959.

3. There is a need for better aircraft maintenance on the test airplane while at Eglin. [redacted] believes that for adequate maintenance at Eglin we need the following: 25X1

- a. An adequate directive.
- b. A highly qualified flight engineer.

[redacted] discussed briefly that [redacted] has not had enough experience on the P2V7 to maintain it adequately. He recommends that we obtain the TIF services of either [redacted] or Hitting for the Phase VI test period. If [redacted] are not available, we will need a Lockheed crew chief type Tech. Rep. to assist aircraft maintenance. [redacted] 25X1 25X1

4. As a result of the decision a year ago, the ABC-49 VHF radios will be installed in all the P2V7's. No action has been taken to obtain kits for field installation of the two (2) FE airplanes. [redacted] will take necessary action to obtain these kits. 25X1

25 YEAR
RE-REVIEW

5. All present agreed that it is best to leave the second EE airplane in storage at Burbank until a definite decision is made on its location. This will probably be 15 July 1959. Major Duckworth will take the action necessary to have Lockheed continue this storage.

6. It was pointed out that the ELINT activity panels in the FE airplanes are different than in the other three (3) airplanes.

7. [] asked if consideration had been given on installation of Cami equipment in the FEV's. This item is under consideration.
ACTION: No recommendations made or action taken.

8. [] stated that he had taken the action necessary to provide support during Phase VI at Eglin from Navy Jacksonville. He also has taken the action necessary to provide support from DAB Burbank during Phase VI modifications.

9. Request all recipients advise the undersigned of errors or omissions in the above.

[]
Major, USAF/DEV. Branch

BPD:DD/P: [] :encl

Distribution:

Orig. - DEV. Branch

2 - DEV. Branch, []

3 - MAT/ANG

4 - OPS/AS

5 - OPS/Room

6 - CI, []

✓ 7 - RI